


Installation Instructions

Part Number: RG1126


1. Strip outer LHD jacket back 2" on 1st end of LHD to be spliced. Cut one of the inner conductors 1" shorter than the other. Strip the inner conductors back 1/2". Repeat on the other LHD cable to be spliced.



2. Slide a Strain Relief connector on the end of each LHD cable. As illustrated.




3. Push Quick Splice In-Line connectors (or single screw terminals) on two of the inner conductors on one of the LHD cable ends until it stops.



4. Slide the splice barrel onto one of the LHD cable ends.



5. Attach the other LHD cable to the opposite end of the Quick Splice In-line connectors (or single screw terminals) to complete the splice.



6. Screw the two strain relief connectors onto the splice barrel and tighten. You have completed your splice.



• Note: The Quick Splice In-Line Connectors have a release and metering port for easy service.

Note: Please refer to all federal, state and local codes, and manufacturer's recommendations prior to design or installation.